

# Table of Contents

<p><b>1 General</b> ..... 1-1</p> <p><b>1.1 Scope</b> ..... 1-2</p> <p><b>1.2 Purpose</b> ..... 1-2</p> <p><b>1.3 Classification</b> ..... 1-2</p> <p><b>1.4 Measurement Units and Applications</b> ..... 1-2</p> <p>1.4.1 Verification of Dimensions ..... 1-2</p> <p><b>1.5 Definition of Requirements</b> ..... 1-2</p> <p>1.5.1 Inspection Conditions ..... 1-3</p> <p>1.5.1.1 Target ..... 1-3</p> <p>1.5.1.2 Acceptable ..... 1-3</p> <p>1.5.1.3 Defect ..... 1-3</p> <p>1.5.1.3.1 Disposition ..... 1-3</p> <p>1.5.1.4 Process Indicator ..... 1-3</p> <p>1.5.1.5 Combined Conditions ..... 1-4</p> <p>1.5.1.6 Conditions Not Specified ..... 1-4</p> <p>1.5.1.7 Uncommon or Specialized Designs ..... 1-4</p> <p>1.5.2 Material and Process Nonconformance ..... 1-4</p> <p><b>1.6 Process Control</b> ..... 1-4</p> <p><b>1.6.1 Statistical Process Control</b> ..... 1-5</p> <p><b>1.7 Order of Precedence</b> ..... 1-5</p> <p>1.7.1 Clause References ..... 1-5</p> <p>1.7.2 Appendices ..... 1-5</p> <p><b>1.8 Terms and Definitions</b> ..... 1-5</p> <p>1.8.1 FOD (Foreign Object Debris) ..... 1-5</p> <p>1.8.2 Inspection ..... 1-5</p> <p>1.8.3 Manufacturer (Assembler) ..... 1-5</p> <p>1.8.4 Objective Evidence ..... 1-5</p> <p>1.8.5 Process Control ..... 1-5</p> <p>1.8.6 Supplier ..... 1-6</p> <p>1.8.7 User ..... 1-6</p> <p>1.8.8 Wire Diameter (D) ..... 1-6</p> <p><b>1.9 Requirements Flowdown</b> ..... 1-6</p> <p><b>1.10 Personnel Proficiency</b> ..... 1-6</p> <p><b>1.11 Acceptance Requirements</b> ..... 1-6</p> <p><b>1.12 Inspection Methodology</b> ..... 1-6</p> <p>1.12.1 Process Verification Inspection ..... 1-6</p> <p>1.12.2 Visual Inspection ..... 1-6</p> <p>1.12.2.1 Lighting ..... 1-6</p> <p>1.12.2.2 Magnification Aids ..... 1-6</p> <p><b>1.12.2.3 Sampling</b> ..... 1-7</p>	<p><b>1.13 Facilities</b> ..... 1-7</p> <p>1.13.1 Field Assembly Operations ..... 1-7</p> <p>1.13.2 Health and Safety ..... 1-7</p> <p><b>1.14 Electrostatic Discharge (ESD) Protection</b> ..... 1-7</p> <p><b>1.15 Tools and Equipment</b> ..... 1-8</p> <p>1.15.1 Control ..... 1-8</p> <p>1.15.2 Calibration ..... 1-8</p> <p><b>1.16 Materials and Processes</b> ..... 1-8</p> <p><b>1.17 Electrical Clearance</b> ..... 1-9</p> <p><b>1.18 Contamination</b> ..... 1-9</p> <p><b>1.19 Rework/Repair</b> ..... 1-9</p> <p>1.19.1 Rework ..... 1-9</p> <p>1.19.2 Repair ..... 1-9</p> <p><b>1.19.3 Post Rework/Repair Cleaning</b> ..... 1-9</p> <p><b>2 Applicable Documents</b> ..... 2-1</p> <p><b>2.1 IPC</b> ..... 2-1</p> <p><b>2.2 Joint Industry Standards</b> ..... 2-1</p> <p><b>2.3 Society of Automotive Engineers (SAE)</b> ..... 2-1</p> <p><b>2.4 American National Standards Institute (ANSI)</b> ..... 2-1</p> <p><b>2.5 International Organization for Standardization (ISO)</b> ..... 2-1</p> <p><b>2.6 ESD Association (ESDA)</b> ..... 2-2</p> <p><b>2.7 United States Department of Defense (DoD)</b> ..... 2-2</p> <p><b>2.8 International Electrotechnical Commission (IEC)</b> ..... 2-2</p> <p><b>2.9 Aerospace Industries Association (AIA/NAS)</b> ..... 2-2</p> <p><b>2.10 Electronics Industries Alliance</b> ..... 2-2</p> <p><b>2.11 ASTM International</b> ..... 2-2</p> <p><b>2.12 Institute of Electrical and Electronics Engineers</b> ..... 2-2</p> <p><b>3 Preparation</b> ..... 3-1</p> <p><b>3.1 Stripping</b> ..... 3-2</p> <p><b>3.2 Strand Damage and End Cuts</b> ..... 3-2</p> <p><b>3.3 Conductor Deformation/Birdcaging</b> ..... 3-5</p>
--	--

## Table of Contents (cont.)

<b>3.4 Twisting of Wires</b> .....	3-7	4.8.3.2 Solder .....	4-34
<b>3.5 Insulation Damage – Stripping</b> .....	3-8	4.8.4 Pierced/Perforated/Punched .....	4-35
<b>4 Soldered Terminations</b> .....	4-1	4.8.4.1 Lead/Wire Placement .....	4-35
<b>4.1 Material, Components and Equipment</b> .....	4-2	4.8.4.2 Solder .....	4-37
4.1.1 Materials .....	4-2	4.8.5 Hook .....	4-38
4.1.1.1 Solder .....	4-2	4.8.5.1 Lead/Wire Placement .....	4-38
4.1.1.1.1 Solder Purity Maintenance .....	4-3	4.8.5.2 Solder .....	4-39
4.1.1.2 Flux .....	4-4	4.8.6 Cup .....	4-41
4.1.1.3 Adhesives .....	4-4	4.8.6.1 Lead/Wire Placement .....	4-41
4.1.1.4 Solderability .....	4-5	4.8.6.2 Solder .....	4-42
4.1.1.5 Tools and Equipment .....	4-5	4.8.7 Series Connected .....	4-45
4.1.2 Gold Removal .....	4-5	4.8.8 Lead/Wire Placement – AWG 30 and Smaller Diameter Wires .....	4-46
<b>4.2 Cleanliness</b> .....	4-6	<b>5 Crimp Terminations (Contacts and Lugs)</b> .....	5-1
4.2.1 Presoldering .....	4-6	<b>5.1 Stamped and Formed – Open Barrel</b> .....	5-3
4.2.2 Postsoldering .....	4-6	5.1.1 Insulation Support .....	5-4
4.2.2.1 Foreign Object Debris (FOD) .....	4-6	5.1.1.1 Inspection Window .....	5-4
4.2.2.2 Flux Residue .....	4-7	5.1.1.2 Crimp .....	5-6
4.2.2.2.1 Cleaning Required .....	4-7	5.1.2 Insulation Clearance if No Support Crimp .....	5-8
4.2.2.2.2 No-Clean Process .....	4-7	5.1.3 Conductor Crimp .....	5-9
<b>4.3 Solder Connection</b> .....	4-8	5.1.4 Crimp Bellmouth .....	5-11
4.3.1 General Requirements .....	4-10	5.1.5 Conductor Brush .....	5-13
4.3.2 Soldering Anomalies .....	4-11	5.1.6 Carrier Cutoff Tab .....	5-15
4.3.2.1 Exposed Basis Metal .....	4-11	5.1.7 Individual Wire Seal .....	5-16
4.3.2.2 Partially Visible or Hidden Solder Connections .....	4-11	<b>5.2 Stamped and Formed – Closed Barrel</b> .....	5-18
<b>4.4 Wire/Lead Preparation, Tinning</b> .....	4-12	5.2.1 Insulation Clearance .....	5-19
<b>4.5 Wire Insulation</b> .....	4-14	5.2.2 Insulation Support Crimp .....	5-19
4.5.1 Clearance .....	4-14	5.2.3 Conductor Crimp and Bellmouth .....	5-21
4.5.2 Postsolder Damage .....	4-16	<b>5.3 Machined Contacts</b> .....	5-23
<b>4.6 Insulation Sleeving</b> .....	4-17	5.3.1 Insulation Clearance .....	5-23
<b>4.7 Birdcaged Wire (Soldered)</b> .....	4-19	5.3.2 Insulation Support Style .....	5-26
<b>4.8 Terminals</b> .....	4-20	5.3.3 Conductor .....	5-27
4.8.1 Turrets and Straight Pins .....	4-23	5.3.4 Crimping .....	5-29
4.8.1.1 Lead/Wire Placement .....	4-23	5.3.5 CMA Buildup .....	5-31
4.8.1.2 Solder .....	4-25	<b>5.4 Termination Ferrule Crimp</b> .....	5-33
4.8.2 Bifurcated .....	4-26	<b>5.5 Shrink Sleeving – Wire Support – Crimped Terminals</b> .....	5-35
4.8.2.1 Lead/Wire Placement – Side Route .....	4-26	<b>6 Insulation Displacement Connection (IDC)</b> .....	6-1
4.8.2.2 Lead/Wire Placement – Bottom and Top Route .....	4-28	<b>6.1 Mass Termination, Flat Cable</b> .....	6-2
4.8.2.3 Lead/Wire Placement – Staked/ Constrained Wires .....	4-30	6.1.1 End Cutting .....	6-2
4.8.2.4 Solder .....	4-31	6.1.2 Notching .....	6-3
4.8.3 Slotted .....	4-33	6.1.3 Planar Ground Plane Removal .....	6-4
4.8.3.1 Lead/Wire Placement .....	4-33	6.1.4 Connector Position .....	6-5
		6.1.5 Connector Skew & Lateral Position .....	6-8
		6.1.6 Retention .....	6-9

## Table of Contents (cont.)

<b>6.2 Discrete Wire Termination</b> .....	6-10	9.3.2 Bonding .....	9-11
6.2.1 General .....	6-10	<b>9.4 Connector Damage</b> .....	9-15
6.2.2 Position of Wire .....	6-11	9.4.1 Criteria .....	9-15
6.2.3 Overhang (Extension) .....	6-12	9.4.2 Limits – Hard Face – Mating Surface .....	9-16
6.2.4 Insulation Crimp .....	6-13	9.4.3 Limits – Soft Face – Mating Surface or Rear Seal Area .....	9-17
6.2.5 Damage in Connection Area .....	6-15	9.4.4 Contacts .....	9-18
6.2.6 End Connectors .....	6-16	<b>9.5 Installation of Contacts and Sealing Plugs into Connectors</b> .....	9-19
6.2.7 Pass Through Connectors .....	6-17	9.5.1 Installation of Contacts .....	9-19
6.2.8 Wiremount Connectors .....	6-18	9.5.2 Installation of Sealing Plugs .....	9-21
6.2.9 Subminiature D-Connector (Series Bus Connector) .....	6-19	<b>10 Over-Molding/Potting</b> .....	10-1
6.2.10 Modular Connectors (RJ Type) .....	6-21	<b>10.1 Over-Molding</b> .....	10-4
<b>7 Ultrasonic Welding</b> .....	7-1	10.1.1 Mold Fill .....	10-4
<b>7.1 Insulation Clearance</b> .....	7-2	10.1.1.1 Inner .....	10-4
<b>7.2 Weld Nugget</b> .....	7-3	10.1.1.2 Outer .....	10-7
<b>8 Splices</b> .....	8-1	10.1.1.2.1 Mismatch .....	10-10
<b>8.1 Soldered Splices</b> .....	8-2	10.1.1.2.2 Fit .....	10-11
8.1.1 Mesh .....	8-3	10.1.1.2.3 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines .....	10-14
8.1.2 Wrap .....	8-5	10.1.1.2.4 Color .....	10-16
8.1.3 Hook .....	8-7	10.1.2 Blow Through .....	10-17
8.1.4 Lap .....	8-8	10.1.3 Position .....	10-18
8.1.4.1 Two or More Conductors .....	8-9	10.1.4 Flashing .....	10-21
8.1.4.2 Insulation Opening (Window) .....	8-12	10.1.5 Wire Insulation, Jacket or Sleeving Damage .....	10-23
8.1.5 Heat Shrinkable Solder Devices .....	8-13	10.1.6 Curing .....	10-24
<b>8.2 Crimped Splices</b> .....	8-15	<b>10.2 Potting (Thermoset Molding)</b> .....	10-25
8.2.1 Barrel .....	8-15	10.2.1 Filling .....	10-25
8.2.2 Double Sided .....	8-18	10.2.2 Fit to Wire or Cable .....	10-29
8.2.3 Contact .....	8-21	10.2.3 Curing .....	10-31
8.2.4 Wire In-Line Junction Devices (Jiffy Junctions) .	8-24	<b>11 Measuring Cable Assemblies and Wires</b> .....	11-1
<b>8.3 Ultrasonic Weld Splices</b> .....	8-25	<b>11.1 Measuring – Cable and Wire Length Tolerance</b> .....	11-2
<b>9 Connectorization</b> .....	9-1	<b>11.2 Measuring – Cable</b> .....	11-2
<b>9.1 Hardware Mounting</b> .....	9-2	11.2.1 Reference Surfaces – Straight/Axial Connectors .....	11-2
9.1.1 Jackpost – Height .....	9-2	11.2.2 Reference Surfaces – Right-Angle Connectors .....	11-3
9.1.2 Jackscrews – Protrusion .....	9-3	11.2.3 Length .....	11-3
9.1.3 Retaining Clips .....	9-4	11.2.4 Breakout .....	11-4
9.1.4 Connector Alignment .....	9-5	11.2.4.1 Breakout Measurement Points .....	11-4
<b>9.2 Strain Relief</b> .....	9-6	11.2.4.2 Breakout Length .....	11-5
9.2.1 Clamp Fit .....	9-6	<b>11.3 Measuring – Wire</b> .....	11-6
9.2.2 Wire Dress .....	9-7	11.3.1 Electrical Terminal Reference Location .....	11-6
9.2.2.1 Straight Approach .....	9-8	11.3.2 Length .....	11-7
9.2.2.2 Side Approach .....	9-9		
<b>9.3 Sleeving and Boots</b> .....	9-10		
9.3.1 Position .....	9-10		

## Table of Contents (cont.)

<b>12 Marking/Labeling</b> .....	12-1	13.10.2.1 Solid .....	13-27
<b>12.1 Content</b> .....	12-2	13.10.2.2 Conformable Cable .....	13-29
<b>12.2 Legibility</b> .....	12-2	13.10.3 Dielectric Cutoff .....	13-30
<b>12.3 Permanency</b> .....	12-4	13.10.4 Dielectric Cleanliness .....	13-32
<b>12.4 Location and Orientation</b> .....	12-5	13.10.5 Center Conductor Pin .....	13-33
<b>12.5 Functionality</b> .....	12-6	13.10.5.1 Point .....	13-33
<b>12.6 Marker Sleeve</b> .....	12-7	13.10.5.2 Damage .....	13-35
12.6.1 Wrap Around .....	12-7	13.10.6 Solder .....	13-36
12.6.2 Tubular .....	12-9	<b>13.11 Swage-Type Connector</b> .....	13-38
<b>12.7 Flag Markers</b> .....	12-10	<b>13.12 Soldering and Stripping of Biaxial/ Multi-Axial Shielded Wire</b> .....	13-39
12.7.1 Adhesive .....	12-10	13.12.1 Jacket and Tip Installation .....	13-39
<b>12.8 Tie Wrap Markers</b> .....	12-10	13.12.2 Ring Installation .....	13-41
<b>13 Coaxial and Biaxial Cable Assemblies</b> .....	13-1	<b>14 Securing</b> .....	14-1
<b>13.1 Stripping</b> .....	13-2	<b>14.1 Tie Wrap/Lacing Application</b> .....	14-2
<b>13.2 Center Conductor Termination</b> .....	13-4	14.1.1 Tightness .....	14-6
13.2.1 Crimp .....	13-4	14.1.2 Damage .....	14-7
13.2.2 Solder .....	13-6	14.1.3 Spacing .....	14-8
<b>13.3 Solder Ferrule Pins</b> .....	13-8	<b>14.2 Breakouts</b> .....	14-9
13.3.1 General .....	13-8	14.2.1 Individual Wires .....	14-9
13.3.2 Insulation .....	13-10	14.2.2 Spacing .....	14-10
<b>13.4 Coaxial Connector – Printed Wire Board Mount</b> .....	13-11	<b>14.3 Routing</b> .....	14-13
<b>13.5 Coaxial Connector – Center Conductor Length – Right Angle Connector</b> .....	13-12	14.3.1 Wire Crossover .....	14-13
<b>13.6 Coaxial Connector – Center Conductor Solder</b> .....	13-14	14.3.2 Bend Radius .....	14-14
<b>13.7 Coaxial Connector – Terminal Cover</b> .....	13-16	14.3.3 Coaxial Cable .....	14-15
13.7.1 Soldering .....	13-16	14.3.4 Unused Wire Termination .....	14-16
13.7.2 Press Fit .....	13-17	14.3.4.1 Shrink Sleeving .....	14-16
<b>13.8 Shield Termination</b> .....	13-18	14.3.4.2 Flexible Sleeving .....	14-17
13.8.1 Clamped Ground Rings .....	13-18	14.3.5 Ties over Splices and Ferrules .....	14-17
13.8.2 Crimped Ferrule .....	13-19	<b>14.4 Broom Stitching</b> .....	14-18
<b>13.9 Center Pin</b> .....	13-21	<b>15 Harness/Cable Electrical Shielding</b> .....	15-1
13.9.1 Position .....	13-21	<b>15.1 Braided</b> .....	15-2
13.9.2 Damage .....	13-22	15.1.1 Direct Applied .....	15-3
<b>13.10 Semirigid Coax</b> .....	13-23	15.1.2 Prewoven .....	15-5
13.10.1 Bending and Deformation .....	13-24	<b>15.2 Shield Termination</b> .....	15-6
13.10.2 Surface Condition .....	13-27	15.2.1 Shield Jumper Wire .....	15-6
		15.2.1.1 Attached Lead .....	15-6
		15.2.1.1.1 Solder .....	15-7
		15.2.1.1.2 Crimp .....	15-11
		15.2.1.2 Shield Braid .....	15-12
		15.2.1.2.1 Woven .....	15-12
		15.2.1.2.2 Combed and Twisted .....	15-12
		15.2.1.3 Daisy Chain .....	15-13
		15.2.1.4 Common Ground Point .....	15-13

## Table of Contents (cont.)

15.2.2	No Shield Jumper Wire .....	15-14	17.3.7.1	Wire/Cable Bundle Sealing Not Required .....	17-19
15.2.2.1	Shield Not Folded Back .....	15-14	17.3.7.1.1	Wire/Cable Sealing Required .....	17-20
15.2.2.2	Shield Folded Back .....	15-15			
<b>15.3</b>	<b>Shield Termination – Connector</b> .....	15-16	<b>18</b>	<b>Solderless Wrap</b> .....	18-1
15.3.1	Shrink .....	15-16	<b>18.1</b>	<b>Number of Turns</b> .....	18-2
15.3.2	Crimp .....	15-18	<b>18.2</b>	<b>Turn Spacing</b> .....	18-3
15.3.3	Shield Jumper Wire Attachment .....	15-20	<b>18.3</b>	<b>End Tails, Insulation Wrap</b> .....	18-4
15.3.4	Soldered .....	15-21	<b>18.4</b>	<b>Raised Turns Overlap</b> .....	18-6
<b>15.4</b>	<b>Shield Termination – Splicing Prewoven</b> .....	15-21	<b>18.5</b>	<b>Connection Position</b> .....	18-7
15.4.1	Soldered .....	15-21	<b>18.6</b>	<b>Wire Dress</b> .....	18-9
15.4.2	Tie/Tape On .....	15-23	<b>18.7</b>	<b>Wire Slack</b> .....	18-10
<b>15.5</b>	<b>Tapes – Barrier and Conductive, Adhesive or Nonadhesive</b> .....	15-24	<b>18.8</b>	<b>Plating</b> .....	18-11
<b>15.6</b>	<b>Conduit (Shielding)</b> .....	15-25	<b>18.9</b>	<b>Damage</b> .....	18-12
<b>15.7</b>	<b>Shrink Tubing – Conductive Lined</b> .....	15-26	18.9.1	Insulation .....	18-12
<b>16</b>	<b>Cable/Wire Harness Protective Coverings</b> .....	16-1	18.9.2	Wires and Terminals .....	18-13
<b>16.1</b>	<b>Braid</b> .....	16-2	<b>19</b>	<b>Testing</b> .....	19-1
16.1.1	Direct Applied .....	16-2	<b>19.1</b>	<b>Nondestructive Tests</b> .....	19-2
16.1.2	Prewoven .....	16-4	<b>19.2</b>	<b>Testing After Rework or Repair</b> .....	19-2
<b>16.2</b>	<b>Sleeving/Shrink Tubing</b> .....	16-6	<b>19.3</b>	<b>Intended Table Usage</b> .....	19-2
16.2.1	Sealant .....	16-7	<b>19.4</b>	<b>Electrical Test</b> .....	19-3
<b>16.3</b>	<b>Spiral Plastic Wrap (Spiral Wrap Sleeving)</b> .....	16-8	19.4.1	Selection .....	19-3
<b>16.4</b>	<b>Wire Loom Tubing – Split and Unsplit</b> .....	16-9	<b>19.5</b>	<b>Electrical Test Methods</b> .....	19-4
<b>16.5</b>	<b>Tapes, Adhesive and Nonadhesive</b> .....	16-9	19.5.1	Continuity .....	19-4
<b>17</b>	<b>Finished Assembly Installation</b> .....	17-1	19.5.2	Shorts .....	19-5
<b>17.1</b>	<b>General</b> .....	17-2	19.5.3	Dielectric Withstanding Voltage (DWW) .....	19-6
<b>17.2</b>	<b>Hardware Installation</b> .....	17-3	19.5.4	Insulation Resistance (IR) .....	19-7
17.2.1	Threaded Fasteners .....	17-4	19.5.5	Voltage Standing Wave Ratio (VSWR) .....	19-8
17.2.1.1	Minimum Torque .....	17-6	19.5.6	Insertion Loss .....	19-8
17.2.2	Wires .....	17-8	19.5.7	Reflection Coefficient .....	19-9
17.2.3	Safety Wiring .....	17-11	19.5.8	User Defined .....	19-9
17.2.4	Safety Cable .....	17-13	<b>19.6</b>	<b>Mechanical Test</b> .....	19-10
<b>17.3</b>	<b>Wire/Harness Installation</b> .....	17-14	19.6.1	Selection .....	19-10
17.3.1	Stress Relief .....	17-14	<b>19.7</b>	<b>Mechanical Test Methods</b> .....	19-11
17.3.2	Wire Dress .....	17-15	19.7.1	Crimp Height (Dimensional Analysis) .....	19-11
17.3.3	Service Loops .....	17-16	19.7.1.1	Terminal Positioning .....	19-12
17.3.4	Clamping .....	17-17	19.7.2	Pull Force (Tensile) .....	19-13
17.3.5	Tie Wrap Lacing .....	17-17	19.7.2.1	Without Documented Process Control .....	19-14
17.3.6	Raceways .....	17-18	19.7.3	Crimp Force Monitoring .....	19-18
17.3.7	Grommets .....	17-19	19.7.4	Crimp Tool Qualification .....	19-18

## Table of Contents (cont.)

19.7.5	Contact Retention Verification .....	19-18	<b>Table 13-1</b>	<b>Coaxial and Biaxial Shield and Center Conductor Damage .....</b>	13-2
19.7.6	RF Connector Shield Pull Force (Tensile) ...	19-19	<b>Table 13-2</b>	<b>Semirigid Coax Deformation .....</b>	13-25
19.7.7	RF Connector Shield Ferrule Torsion .....	19-20	<b>Table 13-3</b>	<b>Dielectric Cutoff .....</b>	13-30
19.7.8	User Defined .....	19-20	<b>Table 14-1</b>	<b>Minimum Bend Radius Requirements .....</b>	14-14
<b>20</b>	<b>High Voltage Applications .....</b>	20-1	<b>Table 17-1</b>	<b>Minimum Swaged Ferrule Pull-Off Load .....</b>	17-13
<b>Appendix A</b>	<b>Terms and Definitions .....</b>	A-1	<b>Table 18-1</b>	<b>Minimum Turns of Bare Wire .....</b>	18-2
<b>Appendix B</b>	<b>Reproducible Test Tables .....</b>	B-1	<b>Table 19-1</b>	<b>Electrical Test Requirements .....</b>	19-3
<b>Appendix C</b>	<b>Guidelines for Soldering Tools and Equipment .....</b>	C-1	<b>Table 19-2</b>	<b>Continuity Test Minimum Requirements .....</b>	19-4
<b>Table A-1</b>	<b>Electrical Clearance .....</b>	A-5	<b>Table 19-3</b>	<b>Shorts Test (low voltage isolation) Minimum Requirements .....</b>	19-5
<b>Table 1-1</b>	<b>Magnification Aids .....</b>	1-7	<b>Table 19-4</b>	<b>Dielectric Withstanding Voltage Test (DWV) Minimum Requirements ...</b>	19-6
<b>Table 1-2</b>	<b>Magnification Aid Applications – Other .....</b>	1-7	<b>Table 19-5</b>	<b>Insulation Resistance (IR) Test Minimum Requirements .....</b>	19-7
<b>Table 3-1</b>	<b>Allowable Strand Damage .....</b>	3-4	<b>Table 19-6</b>	<b>Voltage Standing Wave Ratio (VSWR) Test Parameters .....</b>	19-8
<b>Table 4-1</b>	<b>Maximum Limits of Solder Bath Contaminant .....</b>	4-3	<b>Table 19-7</b>	<b>Insertion Loss Test Parameters .....</b>	19-8
<b>Table 4-2</b>	<b>Solder Connection Anomalies .....</b>	4-11	<b>Table 19-8</b>	<b>Reflection Coefficient Test Parameters .....</b>	19-9
<b>Table 4-3</b>	<b>Turret and Straight Pin Terminal Lead/Wire Placement .....</b>	4-23	<b>Table 19-9</b>	<b>Mechanical Test Requirements .....</b>	19-10
<b>Table 4-4</b>	<b>Bifurcated Terminal Lead/Wire Placement – Side Route .....</b>	4-26	<b>Table 19-10</b>	<b>Crimp Height Testing .....</b>	19-11
<b>Table 4-5</b>	<b>Bifurcated Terminal Lead/Wire Placement – Bottom Route .....</b>	4-28	<b>Table 19-11</b>	<b>Pull Force Testing Minimum Requirements .....</b>	19-14
<b>Table 4-6</b>	<b>Staking Requirements of Side Route Straight Through Connections – Bifurcated Terminals .....</b>	4-30	<b>Table 19-12</b>	<b>Pull Test Force Values .....</b>	19-15
<b>Table 4-7</b>	<b>Pierced or Perforated Terminal Lead/Wire Placement .....</b>	4-35	<b>Table 19-13</b>	<b>Pull Test Force Values (Classes 1 &amp; 2) For UL, SAE, GM and Volvo ...</b>	19-16
<b>Table 4-8</b>	<b>Hook Terminal Lead/Wire Placement ...</b>	4-38	<b>Table 19-14</b>	<b>Pull Test Force Values (Classes 1 &amp; 2) For IEC .....</b>	19-17
<b>Table 4-9</b>	<b>AWG 30 and Smaller Wire Wrap Requirements .....</b>	4-46	<b>Table 19-15</b>	<b>RF Connector Shield Pull Force Testing .....</b>	19-19
<b>Table 10-1</b>	<b>Definitions of Molding/Potting Visual Anomalies .....</b>	10-2			
<b>Table 11-1</b>	<b>Cable/Wire Length Measurement Tolerance .....</b>	11-2			

# 1 Requirements and Acceptance for Cable and Wire Harness Assemblies

## General

The following topics are addressed in this section:

### 1 General

#### 1.1 Scope

#### 1.2 Purpose

#### 1.3 Classification

#### 1.4 Measurement Units and Applications

1.4.1 Verification of Dimensions

#### 1.5 Definition of Requirements

1.5.1 Inspection Conditions

1.5.1.1 Target

1.5.1.2 Acceptable

1.5.1.3 Defect

1.5.1.3.1 Disposition

1.5.1.4 Process Indicator

1.5.1.5 Combined Condition

1.5.1.6 Conditions Not Specified

1.5.1.7 Uncommon or Specialized Designs

1.5.2 Material and Process Nonconformance

#### 1.6 Process Control

1.6.1 Statistical Process Control

#### 1.7 Order of Precedence

1.7.1 Clause References

1.7.2 Appendices

#### 1.8 Terms and Definitions

1.8.1 FOD (Foreign Object Debris)

1.8.2 Inspection

1.8.3 Manufacturer (Assembler)

1.8.4 Objective Evidence

1.8.5 Process Control

1.8.6 Supplier

1.8.7 User

1.8.8 Wire Diameter (D)

#### 1.9 Requirements Flowdown

#### 1.10 Personnel Proficiency

#### 1.11 Acceptance Requirements

#### 1.12 Inspection Methodology

1.12.1 Process Verification Inspection

1.12.2 Visual Inspection

1.12.2.1 Lighting

1.12.2.2 Magnification Aids

1.12.2.3 Sampling

#### 1.13 Facilities

1.13.1 Field Assembly Operations

1.13.2 Health and Safety

#### 1.14 Electrostatic Discharge (ESD) Protection

#### 1.15 Tools and Equipment

1.15.1 Control

1.15.2 Calibration

#### 1.16 Materials and Processes

#### 1.17 Electrical Clearance

#### 1.18 Contamination

#### 1.19 Rework/Repair

1.19.1 Rework

1.19.2 Repair

1.19.3 Post Rework/Repair Cleaning

# 1 Requirements and Acceptance for Cable and Wire Harness Assemblies

## General (cont.)

**1.1 Scope** This standard prescribes practices and requirements for the manufacture of cable, wire and harness assemblies. This standard does not provide criteria for cross-section or X-ray evaluation.

**If a conflict occurs between the English and translated versions of this document, the English version will take precedence.**

IPC/WHMA-A-620 can be used as a stand-alone document for purchasing products; however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

The illustrations in this document portray specific points noted in the title of each section. A brief description follows each illustration. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

**1.2 Purpose** This standard describes materials, methods, tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the related assembly activities associated with cable and harness assemblies.

The intent of this document is to rely on process control methodology to ensure consistent quality levels during the manufacture of products.

Any method that produces an assembly conforming to the acceptability requirements described in this standard may be used.

Standards may be updated at any time, including with the use of amendments. The use of an amendment or newer revision is not automatically required. The revision in effect **shall [D1D2D3]** be as specified by the User.

**1.3 Classification** Use of this standard requires agreement on the Class to which the product belongs. The User has the ultimate responsibility for identifying the Class to which the assembly is evaluated. If the User does not establish and document the acceptance Class, the Manufacturer may do so. Accept and/or reject decisions **shall [D1D2D3]** be based on applicable documentation such as contracts, drawings, specifications, standards and reference documents. Criteria defined in this standard reflect three Product Classes, which are as follows:

### **Class 1 General Electronic Products**

Includes products suitable for applications where the major requirement is the function of the completed assembly.

### **Class 2 Dedicated Service Electronic Products**

Includes products where continued performance and extended life is required, and for which uninterrupted service is desired but not critical. Typically, the end-use environment would not cause failures.

### **Class 3 High Performance/Harsh Environment Electronic Products**

Includes products where continued performance or performance-on-demand is critical, equipment downtime cannot be tolerated, end-use environment may be uncommonly harsh, and the equipment must function when required, such as life support systems and other critical systems.

**1.4 Measurement Units and Applications** This document uses the International System of Units (SI) in accordance with ASTM SI10-10, IEEE/ASTM SI 10, American National Standard for Metric Practice (Section 3). Imperial English equivalent units follow in brackets. The derived SI units used in this document are millimeters (mm) [in] for dimensions and dimensional tolerances, Celsius (°C) [°F] for temperature and temperature tolerances, grams (g) [oz] for weight, and lux (lx) [footcandles] for illuminance.

**1.4.1 Verification of Dimensions** Where not specifically invoked by this standard, actual measurements (e.g. of specific solder fillet dimensions, determination of damage and wrap percentages) are not required except for referee purposes.

**1.5 Definition of Requirements** The word “**shall**” is used in the text of this document wherever there is a requirement for materials, process or acceptance of cable, wire and harness assemblies.